

GSE - Bug #5

EMIRS LabVIEW UART Telemetry Frame Syncing Failure

12/06/2017 02:05 PM - Greg Mathis

Status:	New	Start date:	12/06/2017
Priority:	Normal	Due date:	
Assignee:	Greg Mathis	% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
Description			
When acquiring EMIRS telemetry frames over the UART interface in "frame sync" mode, occasionally frame sync gets lost and doesn't reacquire frame lock.			

History

- #1 - 12/18/2017 07:55 AM - Greg Mathis**
- On 12-13-2017, changed the default UART timeout from 10 to 100 ms for the TLM UART. Ran the "tlmStuckTest.pl script to check for frame sync failures. The test ran for almost 3 hours without a failure. With 10 ms timeout, the test would fail within minutes. This seems promising ...
- #2 - 12/21/2017 09:14 AM - Greg Mathis**
- With UART timeout still set for 100 ms, ran the EM set up overnight, about 14 hours with no error. Was also sending time update commands at 1Hz, 1 PPS, SC1 and SC2 Status commands at 1Hz, while recording raw telemetry. No apparent problems.
- #3 - 12/21/2017 09:25 AM - Greg Mathis**
- With UART timeout set back to 10 ms, and with LabVIEW set for "Realtime priorit" thru the Windows task manager, it still failed within a few minutes, so changing priority didn't help.