

EMIRS - Bug #25

OS Drift during pointing mirror rotation

01/15/2019 04:03 PM - Igor Lazbin

Status:	Resolved	Start date:	01/15/2019
Priority:	Normal	Due date:	
Assignee:	Igor Lazbin	% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
Description			
During mirror rotation prior to acq, there is significant OS_pos drift which takes a long time to correct			

History

- #1 - 01/28/2019 11:42 AM - Igor Lazbin
- Status changed from New to In Progress
-
- #2 - 04/08/2019 10:00 AM - Igor Lazbin
- Status changed from In Progress to Resolved