# EMIRS - Bug #24

## **Extra Data Packets**

01/15/2019 04:02 PM - Igor Lazbin

Status: Start date: Resolved 01/15/2019 **Priority:** Normal Due date: % Done: Assignee: Igor Lazbin 0% Category: **Estimated time:** 0.00 hour Target version: Spent time: 0.00 hour

### Description

While running a Comprehensive Performance Test (CPT) for the record, while installed on the Spacecraft (at LASP), the instrument exhibited an anomalous behavior. The instrument collects the incorrect number of data packages (extra science packets) relative to the issued command. This has been intermittent, sometimes acquiring 1 extra packet, sometimes 2 extra packets, and sometimes no extra packets. Anomaly was also noticed when using the EMIRS\_ACQ command (in Section 4.3.1, step b). Anomaly was also noticed during Aliveness testing.

### **History**

#### #1 - 01/25/2019 05:02 PM - Igor Lazbin

- Status changed from New to In Progress

#### #2 - 04/08/2019 09:59 AM - Igor Lazbin

- Status changed from In Progress to Resolved

07/01/2025 1/1