

EMIRS - Bug #4

Accept Counters in Telemetry Not Working

11/23/2017 05:56 PM - Greg Mathis

Status:	Closed	Start date:	11/23/2017
Priority:	Normal	Due date:	
Assignee:	Jennifer Lazbin	% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
Description There are 3 command accept counters in telemetry: 1. Instrument commands 2. Time Update commands 3. Spacecraft Status commands Instrument command accept counter seems to be working but is showing up in an incorrect location. (in the Time Update Accept count location, I think) I don't think the other 2 commands show up anywhere.			

History

#1 - 12/13/2017 12:10 PM - Anonymous

Verified the accept counters are working on the pender setup with FPGA version 4.6 and software version 2.35_20171127

#2 - 12/13/2017 12:11 PM - Anonymous

- Status changed from New to Closed